



---

# Radial drilling machine

## Description

---

Radial drilling machine with hydraulic clamping system. With IC timer - making it possible to release the arm for up and down movement and stopping the arm with one button. When changing the tool, the spindle can remain in its current position.

### Properties:

- gear wheels in oil bath
- safety device to prevent arm from falling down abruptly
- precision ground gear wheels
- integrated cooling system
- automatic tool ejector
- distance spindle - column: 350 - 1600 mm



## Extra information



---

Item number	30109
Model	CRDM 3050x1600 Topline
EAN	8718242079594
CBS Statistics number	84596990
Article group	Radial drilling machine
Brand	Huvema

Features	Drilling capacity	50 mm
	Tap capacity	M 40
	Distance spindle - column	1600 mm
	Spindle taper	MT 5
	Engine power	3,5 kW
	Voltage	400 V
	Drilling depth	270 mm
	Speed range	56 - 1450 rpm
	Table dimensions	630 x 500 x 500 mm
	Max. distance spindle table	1420 mm
	Column diameter	320 mm
	Power range	0,06 - 0,10 - 0,20 mm/rev
	Number of power supplies	3
	Number of steps	12
	Foot dimensions	2550 x 970 x 200 mm
	Head rotatable	180 °
	Coolant pump	0,2 kW
	Height	2760 mm
	Weight	3300 kg
Packaging dimensions	2670 x 1120 x 2410 mm	

Article group code 349765

# Product images



SPINDLE SPEED 12 STEPS					
1	2	3	4	5	6
100-150	150-200	200-250	250-300	300-350	350-400
400-450	450-500	500-550	550-600	600-650	650-700
700-750	750-800	800-850	850-900	900-950	950-1000
1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600
1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200
2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800
2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400
3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000
4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600
4600-4700	4700-4800	4800-4900	4900-5000	5000-5100	5100-5200
5200-5300	5300-5400	5400-5500	5500-5600	5600-5700	5700-5800
5800-5900	5900-6000	6000-6100	6100-6200	6200-6300	6300-6400
6400-6500	6500-6600	6600-6700	6700-6800	6800-6900	6900-7000
7000-7100	7100-7200	7200-7300	7300-7400	7400-7500	7500-7600
7600-7700	7700-7800	7800-7900	7900-8000	8000-8100	8100-8200
8200-8300	8300-8400	8400-8500	8500-8600	8600-8700	8700-8800
8800-8900	8900-9000	9000-9100	9100-9200	9200-9300	9300-9400
9400-9500	9500-9600	9600-9700	9700-9800	9800-9900	9900-10000

